



Pending

Active

L1: (176) B60R019/22.ipc.

Failed

- (0) ("296/214.ccls.-296/224.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (0) 11 and (stop adj2 block))
- (0) M.E.D.
- (0) ("200/\$.ccls.").CCLS.
- (0) ("188/\$.ccls.").CCLS.
- (0) ("296/\$.ccls.").CCLS.
- (4) golf near2 cart with solar near2 cells
- (0) 296/110.02.ccls.-296/100.05.ccls.
- (0) ("(4662115or4919473or5536060or5924760or
- (0) (296/146.5.ccls.).CCLS.

Saved

- (199) (("49/26.ccls.") or ("49/28.ccls.")).
- (1) ("0000001").PN.
- (0) ("1000001").PN.
- (199) (((("49/26.ccls.") or ("49/28.ccls.")).
- (10) (((("49/26.ccls.") or ("49/28.ccls.")).
- (744) ("318/466").CCLS.
- (744) (("318/466").CCLS.)
- (42) (("318/466").CCLS.) and (sunroof or rc
- (2) (("5899519") or ("5927788")).PN.
- (1) ("5927788").PN.
- (1) ("6024396").PN.
- (1) ("4693507").PN.
- (268) static with build?
- (42) (static with build?) and polyethylene
- (1) charge with dissipat?
- (3369) charge with dissipat?
- (637) (charge with dissipat?) and polyethyl
- (2) ((charge with dissipat?) and polyethyle
- (813) static with dissipat?
- (23) (static with dissipat?) and fuel?

Search

List

Browse

Queue

Clear

DBs

DERWENT

☐ Plurals

Default operator: OR

☒ Highlight all hit terms initially

B60R019/22.ipc.

Drafts

Pending

Active

Failed

Saved

Favorites

Tagged (8)

UDC

Queue

Trash

	U	1	Document ID	Issue Dat	Page	Title	Current
1	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6540275 B1	20030401	55	Structure of the front of a vehicle body	293/24
2	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6435577 B1	20020820	7	Combination bumper skin and under-engine fairin	293/120
3	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 3917332 A	19751104	4	Vehicle fenders of resilient material	293/109
4	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 5066057 A	19911119	6	Bumper structure	293/121
5	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6676179 B2	20040113	14	Front structure of vehicle body	293/115
6	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6648383 B2	20031118	18	Protective structure for vehicles designed	293/120
7	<input type="checkbox"/>	<input checked="" type="checkbox"/>	US 6428065 B2	20020806	10	Bumper structure for automobile	293/121
8	<input type="checkbox"/>	<input checked="" type="checkbox"/>	JP 2002274298	20020925	5	Bumper structure for vehicle e.g. passenger	

Hls

Details


HTML

Structu... Cust... BRS I... IS&R... His Deta... Image Text HTML

123) (static with dissipat?) and fuel?

Flash:

	Type	L #	Hits	Search Text	DBs	Time Stamp	Comment	Error I
1	BRS	L1	176	B60R019/22.ipc.	DERW ENT	2004/06/0 7 13:46		



ISNR:

5 BRS: bumper with bracket with

BRS:

BRS: 11 and

⌚ Pending

L1:

L3: (0) (293/187.04).CCLS

Failed

(0) ("296/\$.ccls.") .CCLS.

```

3 (0) 11 and (stop adj2 blo

```

(0) (11200/

(0) ("296/\$.ccls.").CCLS.

(0) 296/110.02.ccls.-296/

(0) (296/146.5.ccls.) .CCLS.

 Favorites

UDC

Trash

1

100

1

Page 10 of 10

Ⓢ Pendi

Failed

 Fiori

UDC

Ready

Clear

USPAT


☒ Highlight all hit terms initially

296/187.04



	U	1	Document ID	Issue Dat	Page	Title	Current C
1	U	1	US 6540275	20030401	55	Structure of the front of a vehicle body	293/24
2	U	1	US 6435577	20020820	7	Combination bumper skin and under-engine fairin	293/120
3	U	1	US 3917332	19751104	4	Vehicle fenders of resilient material	293/109

 HTML



296/187.04

 Structur...
 Custo...
 BRS...
 IS&R...
 His
 Data...
 Image
 Text
 HTML

	Type	L.#	Hits	Search Text	DBs	Time Stamp	Comment	Error
1	IS&R	L1	75	(293/109).CCLS.	USPA T	2004/06/0 7 12:11		
2	IS&R	L2	311	(293/146).CCLS.	USPA T	2004/06/0 7 12:14		
3	IS&R	L3	0	(293/187.04).CCLS.	USPA T	2004/06/0 7 12:14		
4	IS&R	L4	22	(296/187.04).CCLS.	USPA T	2004/06/0 7 12:14		

 Hits
 Details
 HTML